



TRITON
RESTORATION LIMITED

The Royal Exchange Threadneedle street, London, EC2

Triton were awarded the Main Contract to undertake a geophysical survey of all the statuary and an inspection of over 400 stone roses to the cornice before carrying out all essential stone restoration works. Access was facilitated using a MEWP where required, and certain activities were undertaken out of hours to suit site constraints.

Of the statuary, only the 3 metre high statue of “Commerce” was found to be in a poor condition. The neck and shoulders were severely fractured and were re carved in Perryfield Whitbed Portland limestone.



A variety of details were also re carved, including fingers and noses, and wall panels replaced with a matching finish.

serious trip hazard.

Triton were re appointed in January 2005 to undertake cleaning and repairs to the east tower. This work comprised fixing of over 70 stone indents with new stainless steel cramps, restoration mortar repairs as necessary, redecoration of previously painted surfaces and remedial works to the entrance portico, where differential weathering of York stone paving and asphalt grouting had left a

